

AD-A155 156


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
WATER LOOM POND DAM (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV FEB 79


1/1

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART
 10X 1000-10000

AD-A155 156

DTIC ACCESSION NUMBER

II

LEVEL

PHOTOGRAPH THIS SHEET

INVENTORY

WATER LOOM POND DAM

DOCUMENT IDENTIFICATION

Feb 1979

This document has been approved
for public release and sale; its
distribution is unlimited.

DISTRIBUTION STATEMENT

ACCESSION FOR

NTIS GRA&I

DTIC TAB

UNANNOUNCED

JUSTIFICATION

☒
☐
☐

BY

DISTRIBUTION

AVAILABILITY CODES

DIST

AVAIL AND/OR SPECIAL

A-1

DISTRIBUTION STAMP

DTIC
ELECTE
JUN 19 1985
S E

DATE ACCESSIONED

DATE RETURNED

DATE RECEIVED IN DTIC

REGISTERED OR CERTIFIED NO.

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDAC

MERRIMACK RIVER BASIN
NEW IPSWICH, NEW HAMPSHIRE

WATER LOOM POND DAM
NH 00355
NHWRB 175.09

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

FEBRUARY 1979

AD-A155 156

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NH 00355	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Water Loom Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE February 1979
		13. NUMBER OF PAGES 63
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Merrimack River Basin New Ipswich, New Hampshire Souhegan River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a 204 ft. long earth fill, concrete gravity and stone masonry structure on the Souhegan River. It is about 22.5 ft. high with its 75 ft. long spillway having a height of about 19 ft. It is small in size with a significant hazard potential. The dam is in poor condition and requires considerable routine maintenance. There are various remedial measures which must be implemented by the owner.		

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

WATER LOOM POND DAM
NH 00355

MERRIMACK RIVER BASIN
NEW IPSWICH, NEW HAMPSHIRE

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

PHASE I REPORT

Identification No.: NH 00355
NHWRB No.: 175.09
Name of Dam: WATER LOOM POND DAM
Town: New Ipswich
County and State: Hillsborough County, New Hampshire
Stream: Souhegan River
Date of Inspection: November 14, 1978

BRIEF ASSESSMENT

Water Loom Pond Dam is a 204 foot long earth fill, concrete gravity, and stone masonry structure on the Souhegan River in New Ipswich, New Hampshire. The total dam height is about 22.5 feet with its 75 foot long spillway having a height of about 19 feet. A sluice gate at the right abutment is no longer operable while a former outlet to a six foot penstock has been filled in with earth. The dam is presently owned by Warwick Mills. Some sort of dam has probably existed on the site since about 1827.


The dam was used to supply power to various mills downstream of the dam, but it is not presently being used to supply power. The drainage area is 23.1 square miles of primarily forested terrain. The dam's maximum impoundment of less than 1000 acre-feet and height of less than 40 feet place it in the SMALL size category, while the possibility of damage to downstream structures in the event of a failure with little threat of loss of life result in a SIGNIFICANT hazard potential classification. Based on the size and hazard classification, and in accordance with the Corps' guidelines, the Test Flood (TF) is taken as the 100-year flood.

A TF at the dam of 4000 cfs was chosen. This discharge corresponds to a water level of 4.9 feet above the spillway crest or about 1.4 feet above the left side of the dam.

The dam is in POOR condition and requires considerable routine maintenance. It is recommended that the owner retain the services of a registered professional engineer to rehabilitate the sluice gate structure and restore it to operating conditions; to repair eroded and spalled concrete on all facing walls, abutments, and at the spillway base; and to monitor seepage at the penstock and right abutment structure to determine necessary remedial

measures. Recommended remedial measures include clearing of brush and trees on downstream slopes, completely severing the penstock at its emergence through the downstream side of the dam, instituting a program of annual technical inspections, clearing debris and overhanging trees from the downstream channel, and preparing a formal flood and emergency warning system.

The recommendations and improvements outlined above should be implemented within one year of receipt of the report by the owner.



William S. Zolno

William S. Zolno
N.H. Registration 3226



Nicholas A. Campagna, Jr.

Nicholas A. Campagna, Jr.
California Registration 21006

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the Test Flood should not be interpreted as necessarily posing a highly inadequate condition. The Test Flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

	<u>Page</u>
LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	
REVIEW BOARD SIGNATURE SHEET	
PREFACE	iv
TABLE OF CONTENTS	v
OVERVIEW PHOTOS	vii
LOCATION MAP	ix
 SECTION 1 - PROJECT INFORMATION	
1.1 General	1-1
1.2 Description of Project	1-2
1.3 Pertinent Data	1-5
 SECTION 2 - ENGINEERING DATA	
2.1 Design Records	2-1
2.2 Construction Records	2-1
2.3 Operational Records	2-1
2.4 Evaluation of Data	2-1
 SECTION 3 - VISUAL OBSERVATIONS	
3.1 Findings	3-1
3.2 Evaluation	
 SECTION 4 - OPERATIONAL PROCEDURES	
4.1 Procedures	4-1
4.2 Maintenance of Dam	4-1
4.3 Maintenance of Operating Facilities	4-1
4.4 Description of Warning System	1-1
4.5 Evaluation	4-1

Table of Contents - Cont.


	<u>Page</u>
SECTION 5 - HYDRAULICS/HYDROLOGY	
5.1 Evaluation of Features	5-1
5.2 Hydrologic/Hydraulic Evaluation	5-1
5.3 Downstream Dam Failure Hazard Estimate	5-1
SECTION 6 - STRUCTURAL STABILITY	
6.1 Evaluation of Structural Stability	6-1
SECTION 7 - ASSESSMENT, RECOMMENDATIONS, AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-2
7.4 Alternatives	7-2
<u>APPENDICES</u>	
APPENDIX A - VISUAL INSPECTION CHECKLIST	A-1
APPENDIX B - FIGURES AND PERTINENT RECORDS	B-1
APPENDIX C - SELECTED PHOTOGRAPHS	C-1
APPENDIX D - HYDROLOGIC/HYDRAULIC COMPUTATIONS	D-1
APPENDIX E - INFORMATION AS CONTAINED IN <u>THE NATIONAL INVENTORY OF DAMS</u>	E-1



Overview of left side of dam and abandoned inlet
from upstream left side



Overview of dam from right abutment



Overview of spillway from upstream left side

SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedure

At present the dam is not operated. Water flows in an uncontrolled manner over the spillway. None of the control facilities is operable.

4.2 Maintenance of Dam

The dam is not being maintained. The poor condition of the concrete at the dam is direct evidence of this.

4.3 Maintenance of Operating Facilities

The old penstock outlet has been sealed with earth fill, and the sluice gate has not been maintained and is no longer operable.

4.4 Description of Warning System

No warning system is in effect for this dam.

4.5 Evaluation

The dam's present POOR condition is a direct result of the lack of maintenance of the dam and its facilities. The severe deterioration of the concrete on the spillway, abutment structures and facing walls is an example of this. The sluice gate is not operable because of the lack of maintenance.

Failure of this steel riveted penstock at this location could possibly cause translation and rotation of the penstock through the earth embankment. Seepage at the rate of 1 gpm was observed through the penetrated invert.

3.2 Evaluation

Water Loop Pond Dam is rated in POOR condition based primarily upon the deteriorated condition of the concrete. The concrete lining for the earth embankment on the left side of the dam is severely eroded as it is on other parts of the dam. In general, the dam's major components are efficiently accessible to permit a satisfactory visual inspection.

Seepage at the rate of 1 gpm flows through the interface of the downstream base of the structure and bedrock.

(6) Gate Structure

This gate is no longer operable. Observations have revealed that the timber sluice gate has deteriorated to the extent that seepage flows through and around the gate. This seepage is at the rate of approximately 15 to 20 gpm. In addition, the timber gate stem is broken and rotted and the operating mechanism is rusted with no evidence of maintenance.

The concrete in the roof of the sluiceway outlet structure is severely exuded and has significant stalactite formation. Both side walls of this structure are highly effloresced. The base of the walls of this structure are spalled and deteriorated. A detailed inspection of the extreme deterioration of the upstream face of this structure has revealed that this structure was constructed with random stone masonry and later faced with concrete. Dislodged stones observed below water level would preclude the operation of the sluice gate.

(7) Right End Wall

The top surface of this structure is spalled and is randomly cracked over its entire area. The upstream face is also severely spalled. This spalling is attributed to moisture intrusion and the action of alternate freeze and thaw cycles.

(8) Penstock

Failure of the supporting piers carrying the penstock over the outlet channel would conceivably increase the rate of seepage through the earth embankment and become a potential hazard. Observations have revealed that the penstock freely spans over the abandoned foundation wall and then over two piers spanning the outlet channel. The right pier, which is approximately 10 feet high, is out of plumb by approximately 6 inches.

(3) Left Spillway Abutment and Downstream Training Wall

Approximately 25% of the top surface area of the left abutment has spalled. The vertical surface of this wall is extensively spalled and deteriorated over 50% of its surface area. The intersection between the abutment's vertical plane with the spillway crest has eroded along the contour of the crest for a distance of approximately 4 feet. The depth of the erosion is up to 6 inches. This erosion is attributed to ice damage and cavitation. The left downstream training wall has a series of horizontal cracks and points of efflorescence. The randomly placed stone masonry training wall does not have any visual deficiencies.

(4) Spillway Structure

Inspection of the downstream face of the spillway structure revealed that there are a series of open construction joints with minor evidence of erosion, which is attributed to cavitation. However, there are two areas where erosion is severely pronounced. These areas are located at the spillway center and right quarter point of the spillway base. The eroded concrete at the center of the spillway is approximately 8 feet long, 2 feet high, and 6 inches deep. The erosion at the quarter point is approximately 8 square feet in surface area and approximately 3 inches deep. The erosion at these two locations is attributed to cavitation of improperly mixed concrete.

(5) Right Abutment Structure

This structure is severely eroded and spalled. The upstream side of this structure has been eroded to depths of 15 inches at the spillway crest elevation, exposing rubble stone masonry from previous constructions. This erosion continues along the interface of the structure and the ogee crest and is about 9 to 12 inches in depth. The vertical faces of the structure are spalled from a depth of approximately 4 inches below the water line to near the top surface of the structure. The erosion and spalling is attributed to ice damage, cavitation, and alternate freeze and thaw cycles. Random cracking and efflorescence is prevalent over the vertical and horizontal surfaces of this structure. A close inspection of this structure has revealed that concrete topping and facing repairs had been instituted in the past which accounts for the uniform depth of spalling.

SECTION 3 - VISUAL OBSERVATIONS

3.1 Findings

(a) General

Water Loom Pond Dam is in POOR condition. This evaluation is based primarily on the deterioration of various structural components of the dam. This structure requires extensive maintenance type repairs to allow its continued long-term use.

(b) Dam

(1) Left Facing Wall

The front face of this wall has spalled or eroded over its entire length. In some cases, the erosion is 2 feet high and 12 inches deep. Immediately to the left of the first angle point of this wall the erosion and spalling of the face of the wall is in excess of 4 feet in height and 6 inches deep at the water line. Reinforcing steel is exposed in this area. Reinforcing steel is also exposed over approximately 25' of the length of the wall at the spillway crest elevation. The section of the wall adjacent to the abandoned outlet structure, which is approximately 15 feet long, exhibits erosion over two thirds of its face. This erosion is to a depth of 4 or 5 inches. The top surface of the entire wall has spalls over approximately 5% of its area and has much random cracking. The erosion and spalling along the entire face of this facing wall is attributed to wave action, ice damage, and alternate freeze and thaw cycles.

The entrance opening to the penstock has been blocked off with wood planking and earth backfill within the training walls. The penstock gate is no longer operable. Minor seepage at the rate of 1 gpm was observed through the invert opening of the penstock adjacent to the abandoned building foundation wall.

(2) Left Earth Embankment

The earth embankment on the downstream side of the left facing wall shows no evidence of vertical or horizontal movement. The downstream slope is covered with heavy brush and a few trees. This makes inspection of the slope difficult. This slope should be inspected again after the trees and brush have been cleared. There was no evidence of trespassing on the slopes.

SECTION 2 - ENGINEERING DATA

2.1 Design Records

The design of the dam is not complex and incorporates no unusual features. No design drawings or calculations of value were available for this dam.

2.2 Construction Records

No construction records are available for the dam.

2.3 Operational Records

No operational records of value are available for the dam.

2.4 Evaluation of Data

(a) Availability

The absence of any meaningful design data and calculations leads to an unsatisfactory assessment for availability.

(b) Adequacy

The lack of in-depth engineering data does not permit a definitive review. Therefore, the adequacy of the dam cannot be assessed from the standpoint of reviewing design and construction data. This assessment is based primarily on the visual inspection, past performance, and sound engineering judgment.

(c) Validity

The observations of the inspection team generally confirm the information contained in files of the New Hampshire Water Resources Board. Therefore, although the data is very limited, a satisfactory evaluation for validity is indicated.

- (4) Spillway crest: 927.7
- (5) Invert of sluice gate (inoperable): 921 +
- (6) Streambed at low point: 908.9 ±

(d) Reservoir

- (1) Length of pool - recreational: 8300 feet +
- maximum: 10,100 feet +
- (2) Storage - recreational pool: 420 acre-feet +
- maximum pool: 665 acre-feet +
- (3) Surface area - recreational pool: 70 acres +
- maximum pool: 75 acres +

(e) Dam

- (1) Type: Earthfill embankment with a concrete facing and a gravity concrete spillway
- (2) Length: 204 feet +
- (3) Height: 22.5 feet
- (4) Top Width: Varies
- (5) Side slopes: Vary

(f) Spillway

- (1) Type: Ogee gravity concrete
- (2) Length of weir: 75 feet
- (3) Crest elevation: 927.7
- (4) Gates: None operable
- (5) U/S channel: Wide approach from pond
- (6) D/S channel: Rocky river channel with overhanging vegetation

(g) Regulating Outlet

See Section 1.3 (b) (1) of this report.

(i) Normal Operational Procedure

No operation is performed at the dam. Water flows over the spillway in an uncontrolled manner.

1.3 Pertinent Data

(a) Drainage Area

Water Loom Pond receives runoff from 23.1 square miles of primarily steeply sloping forested terrain. Developing areas comprise only a small portion of the drainage area.

(b) Discharge at Damsite

(1) Outlet Works

The outlet works consist of a 16 foot wide inlet that used to supply the 6 foot penstock that led to the mills downstream and a grated sluiceway approximately 3 feet wide by 3 feet high. Neither of these outlet works is presently operable.

(2) Maximum Flood

The flow during the storm of March 1936 evidently exceed 5000 cfs. It should be noted, however, that since that time a number of flood control dams have been built on tributaries to the Souhegan River, including at least two upstream of Water Loom Pond.

(3) Spillway capacity at maximum pool elevation:

1950 cfs at El. 931.2 (This includes some flow - 110 cfs over the right side of the dam)

(c) Elevation (Feet above MSL)

(1) Top of dam: 931.2

(2) Maximum pool: 931.2

(3) Recreational pool: 927.7

(d) Hazard Potential Classification

Water Loom Pond Dam is considered to fall within the SIGNIFICANT hazard potential classification. This is based mainly on the possibility of some damaging flooding in downstream Greenville and also the remote possibility of damaging Otis Company Dam No. 1 (NH 00041) downstream. The potential for loss of life in the event of a dam failure is considered remote.

(e) Ownership

Columbia Manufacturing owned the mills and dam from 1838 until they went bankrupt in 1924 at which time they sold their holdings to Consolidated Textiles. Consolidated Textile closed the mills and dam. In 1936 Warwick Mills purchased the dam and several mills and still owns the dam. Their address is Warwick Mills, Greenville, New Hampshire.

(f) Operator

Warwick Mills operates the dam through its plant manager, Mr. Roger Laferrier. He can be reached by telephone at 603-878-1565.

(g) Purpose of Dam

The original purpose of the dam was to provide power for the mills downstream from the dam. At present there is no readily identifiable purpose for the dam although it may serve some recreational purpose in this rural location. The last power was generated in the mid 1960's.

(h) Design and Construction History

The dam was built in conjunction with mill construction. The first mill was built in 1827 and burned in 1848. The second mill was built in 1849 and burned in 1871. The third mill at the site was built in 1878. No data is available on when the original dam was built, but it was probably built in conjunction with the original mill. Data supplied by Mr. Laferrier indicated that the dam was rebuilt in 1840 and that concrete was added to the structure in 1948-1949. Other data suggests that modifications in 1925 and 1930, which consisted of facing the abutments with concrete, shortened the spillway by about 10 feet.

The upstream face of the earth-filled dam has a concrete facing. The width at its top surface varies from 15 inches to 2 feet. A dry stone masonry wall is located approximately 15 feet downstream and is parallel to this concrete facing. The right end of this wall is stone masonry and forms part of the left end of the spillway.

The left end wall of the spillway consists of a squared stone masonry structure approximately 10 feet wide and is partially buried on its downstream side. The front face of this end wall consists of a 4 foot wide cement concrete structure. The downstream training wall is approximately 10 feet wide, 30 feet long, and is constructed with squared stone masonry. A concrete apron approximately 8 feet square is located at the downstream base of this end wall.

The spillway is approximately 19 feet high at its maximum and is founded on bedrock. The crest of the spillway is approximately 3.5 feet below the top of the left side of the dam. There are no provisions for flashboards along its crest.

The right abutment structure is a concrete-faced stone masonry structure 11 feet in width and approximately 15.5 feet in length. Its top elevation is approximately one foot lower than the left side of the dam. The downstream end of the abutment structure is 5 feet in width and approximately 17 feet in length. This structure is founded on bedrock. A gate structure with a 3.5 foot by 32 inch sluiceway opening is located to the right of the abutment structure. An end wall, which is parallel to the spillway axis and approximately 26 feet long and 5 feet wide, extends from the side of the abutment structure to the right bank. This wall is founded on bedrock. The sluiceway outlet has been cut through bedrock and diverts the flow back into the downstream channel below the spillway. The sluice gate structure consists of a 3 foot square timber gate and a timber stem with a single rack gear. The rack gear is operated by a spindle gear which is manually driven by a ratchet.

(c) Size Classification

The dam's maximum impoundment of 665 acre-feet is less than 1000 acre-feet and its height of 22.5 feet is less than 40 feet. This places the dam in the SMALL category according to the "Recommended Guidelines" of the Corps of Engineers.

1.2 Description of Project

(a) Location

Water Loom Pond Dam lies on the Souhegan River in the town of New Ipswich, N.H. The dam is located approximately 3000 feet upstream from the crossing of Routes 123 and 124 over the Souhegan River in New Ipswich. The dam is accessible from River Road which intersects Routes 123 and 124 near the center of New Ipswich. The portion of the USGS Ashley, MA-NH quadrangle presented previously shows this locus. Figure 1 of Appendix B presents a detail of the site developed from the inspection visit and the map.

(b) Description of Dam and Appurtenances

The dam and appurtenances consist of a concrete-faced earth embankment, a concrete ogee type spillway, a sluice gate, and an abandoned penstock outlet. The penstock leads downstream to the location of a former mill building and then downstream for a distance of approximately 1.2 miles to other mills.

The overall length of the dam is approximately 214 feet. Approximately 102 feet of this length is left of the spillway. The spillway itself is approximately 75 feet in length. The remaining portion of the dam consists of the right end wall of the dam.

A former outlet structure is located at the extreme left end of the dam adjacent to the left bank. This outlet structure consists of dry stone masonry training walls forming an entrance bay which has since been filled in with earth. Observations of the remains of the mill foundations immediately downstream have revealed the presence of two stone arches in its walls which indicates the presence of a former sluiceway. It is apparent that the abandoned outlet was the source of the water supply to the former mill building. At a later date a 6 foot diameter steel riveted penstock was placed in the former sluiceway and the trench was filled. A gate stem is located at the former outlet which controlled the flow of water into the penstock.

PHASE I INSPECTION REPORT

WATER LOOM POND DAM

SECTION 1

PROJECT INFORMATION

1.1 General

(a) Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Goldberg, Zoino, Dunnicliff & Associates, Inc. (GZD) has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire. Authorization and notice to proceed was issued to GZD under a letter of November 28, 1978 from Colonel Max B. Scheider, Corps of Engineers. Contract No. DACW 33-79-C-0013 has been assigned by the Corps of Engineers for this work.

(b) Purpose


(1) Perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.

(2) Encourage and prepare the states to initiate quickly effective dam safety programs for non-federal dams.

(3) Update, verify, and complete the National Inventory of Dams.

(c) Scope

The program provides for the inspection of non-federal dams in the high hazard potential category based upon location of the dams and those dams in the significant hazard potential category believed to represent an immediate danger based on condition of the dam.



— SCALE —
0 1000 2000 4000 FT

FROM: USGS ASHBY, N.H. - MASS
QUADRANGLE MAP

GOLDBERG, ZOINO, DUNNICLIFF & ASSOC, INC
GEOTECHNICAL CONSULTANTS
NEWTON UPPER FALLS, MASS.

U.S. ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS

LOCUS PLAN

FILE No. 2201

WATER LOOM POND DAM

NEW HAMPSHIRE

SCALE AS NOTED

DATE NOVEMBER 1978

SECTION 5 - HYDRAULICS/HYDROLOGY

5.1 Evaluation of Features

(a) Design Data

Data sources available for Water Loom Pond Dam include prior inventory and inspection reports. The New Hampshire Water Control Commission's "Data on Dams in New Hampshire" (April 17, 1939), "Data on Reservoirs and Ponds in New Hampshire" (undated), and "Data on Water Power Developments in New Hampshire" (April 17, 1939) as well as the New Hampshire Water Resources Board's "Inventory of Dams and Water Power Developments" (October 29, 1937) provide much of the basic data for the dam. Inspection reports from June 26, 1930, July 3, 1951, and September 21, 1974, a series of undated Water Power Questionnaires and a "Report upon (the proposed) Water Loom Pond Storage Project" (March 1, 1935) by the Advisory Committee on Conservation are also available.

(b) Experience Data

Data on lake levels in Water Loom Pond is available in the U.S. Geological Survey (USGS) Water Supply Papers 798 and 867, which report peak flood levels experienced during major storms in March, 1936 and September 1938; and a Water Control Commission questionnaire completed by the dam's owners concerning the 1938 event. The USGS reports peak levels 5.7 feet and 2.9 feet above the spillway crest in 1936 and 1938. The owners of the dam estimated the peak in 1938 to be about 4 feet above the spillway.

Estimates of peak discharges for the two floods at Greenville, about 1.8 miles downstream, are published in the Water Supply Papers referred to above. The 1936 estimated peak was 6160 cfs and the 1938 value was 4970 cfs.

(c) Visual Observations

Water Loom Pond Dam is a concrete, earth fill, and stone masonry structure on the Souhegan River at New Ipswich, New Hampshire. The spillway is of mass concrete with an ogee-shaped crest. The crest length is 75 feet at elevation 927.7 feet above Mean Sea Level (MSL). A concrete gravity wall extends to the right of the spillway for a distance of about 38 feet with top elevation

2.5 feet above the spillway crest. To the left of the spillway an earthfill embankment, retained by a concrete wall on the upstream side and by a squared stone masonry wall on a portion of the downstream side. The top of the left side of the dam is at elevation 131.2 feet above MSL.

Other dam appurtenances include a sluiceway and a penstock. The sluiceway, just to the right of the spillway, has dimensions approximately 3 feet by 3 feet. It is sealed by a gate which is presently inoperable. The 6-foot diameter steel penstock is no longer in service and has been cut at the site of an old mill (since demolished) just below the dam. The 16-foot wide penstock inlet near the left abutment is sealed with sand and gravel.

Downstream of the dam, the Souhegan River channel is relatively steep and narrow. The penstock is elevated to cross the stream channel shortly downstream of the spillway. About 3000 feet further downstream, the river is crossed by High Bridge. This is a cemented stone masonry structure approximately 25 feet thick and extending upwards perhaps 50 feet above the streambed. The stream passes through a rectangular-shaped culvert with an arched top of dimensions approximately 11.6 feet wide by 23 feet high.

About 600 feet downstream of High Bridge, a small concrete over flow structure has been built across the stream, backing up water to a depth of about 10 feet at High Bridge. There is an operating mill building adjacent to the dam approximately 12 feet above the crest level.

Below this structure, the Souhegan River enters a low, flat swampy area, over a half mile long and over a quarter mile across. The stream then reenters a narrow channel for about a half mile before entering a small, seven-acre, impoundment behind the Otis Company Dam in Greenville. This dam, located in the center of the town, is a 26-foot high masonry structure.

(d) Overtopping Potential

The hydrologic conditions of interest in this Phase I investigation are those required to assess the dam's overtopping potential and its ability to safely allow an appropriately large flood to pass.

This requires using the discharge and storage characteristics of the structure to evaluate the impact of an appropriately-sized Test Flood. None of the original hydraulic and hydrologic design records are available for use in this study.

Guidelines for establishing a recommended Test Flood based on the size and hazard classifications of a dam are specified in the "Recommended Guidelines" of the Corps of Engineers. The appropriate Test Flood for a dam that is SMALL in size with a SIGNIFICANT hazard potential would be between the 100-year flood and one-half of the Probable Maximum Flood (PMF). Where a range of values is indicated for the Test Flood, the magnitude should be related to the hazard potential. Since the hazard potential is on the low side of the SIGNIFICANT category, the test inflow to Water Loom Pond is taken to be the 100-year flood.

As there is no streamflow record or previous study available for this site, the magnitude of the 100-year flood has been estimated using the regression relations developed by Denis R. LeBlanc in the USGS publication, Progress Report on Hydrologic Investigations of Small Drainage Areas in New Hampshire. By this method, the 100-year peak inflow is estimated at 2230 cfs.

Additionally, a 1978 FIS study by ANCO estimated the 100-year and 500-year peak discharges at Greenville, approximately 1.8 miles downstream, to be 1885 cfs and 3600 cfs respectively.

Historic floods at the site have also been considered. The flow during the storm of March 1936 evidently exceeded 5000 cfs, while contradictory evidence for the September 1938 flood indicates that the peak discharge may have been as high as 4100 cfs or it may have been no greater than 1500 cfs. It should be noted, however, that since the time of these floods, a number of flood control dams have been built on tributaries to the Souhegan River, including at least two upstream of Water Loom Pond.

Given the wide range of flood discharge values under consideration, an appropriately conservative Test Flood magnitude of 4000 cfs was chosen.

The Test Flood of 4000 cfs is taken to be the value at the dam as modified by flow through the storage in Water Loom Pond. Although no direct storage routing is considered, a storage-stage curve is developed assuming that storage above the full dam level is equal to the lake area times the depth of surcharge. No spreading or increase of area with depth is considered.

The stage-discharge curve is developed by defining discharge as the sum of flow over the spillway, flow over the dam crest, and flow over the side slopes at the ends of the dam. The calculations determining these curves are included in Appendix D.

The peak test discharge of 4000 cfs would result at a maximum stage of 4.9 feet above the spillway crest, or 1.1 feet above the top of the dam (left side).

5.2 Hydrologic/Hydraulic Evaluation

The results of the hydrologic and hydraulic calculations indicate that the dam would be slightly overtopped for the recommended Test Flood. A potential depth of overtopping of 1.1 feet is indicated. It should perhaps be noted here that the dam has previously been overtopped by a greater depth in 1936 without sustaining serious damage. It is uncertain if the dam is in an equivalent state of repair at this time.

5.3 Downstream Dam Failure Hazard Estimates

The peak outflow at Water Loom Pond Dam that would result from dam failure is estimated using the procedure suggested in the Corps of Engineers New England Division's April 1978 "Rule of Thumb Guidelines for Estimating Downstream Dam Failure Hydrographs." Failure is assumed to occur as soon as the dam crest is overtopped at an elevation of 131.2 feet. This is 3.5 feet above the spillway and some 22 feet above the streambed. It is assumed that a 30 foot gap is opened in the dam - the peak failure outflow through this gap and over the spillway would be 5400 cfs.

This flow would not be significantly attenuated along the reach from the dam to High Bridge for the channel is relatively steep and narrow. Flow depths of about 8.5 feet would be expected, but there are no operating structures along this reach to be considered.

At High Bridge, the 11.6 foot by 23 foot culvert would act as a constriction to the flow and cause backwater ponding immediately upstream. It is estimated from calculations

essentially following the Corps of Engineers guidelines that temporary storage upstream of High Bridge would attenuate the flood peak to 4800 cfs. The estimated peak flood level at High Bridge of 30 feet above the streambed (some 20 feet below the roadway) is not considered a hazard to the structures since it appears that flows of this magnitude have occurred in the past.

The small concrete overflow structure downstream of High Bridge would probably not be adversely affected by the dam failure flood wave. Neither would it impound a large enough volume of water to significantly reduce the peak. At 4800 cfs, the estimated overflow head of 8.3 feet would leave peak flood levels about 4 feet below the level of the nearby mill building.

Further downstream, the flood wave would be significantly attenuated in passing through the flat, swampy area because of the large potential for temporary storage there. It is assumed that the peak flow rate would be reduced in this reach from 4800 cfs to about 4000 cfs. Assuming minimal attenuation in the narrow channel beyond the swamp and in the small impoundment behind Otis Company Dam, the peak discharge at Otis Company Dam because of the hypothesized failure of the Water Loop Pond Dam is estimated at 4000 cfs.

To pass this 4000 cfs flow, the head above the spillway crest must be about 5.5 feet. In this case, a portion of the dam to the left of the spillway will be overtopped to a depth of 1.7 feet while the left abutment will be overflowed to a depth of 0.7 feet causing some damaging, but probably not dangerous, flooding in the town of Greenville. The consequences of such flood depths at the Otis Company Dam are uncertain. Failure of this dam could be very serious because of its location in a built-up area; however, a Water Control Commission questionnaire completed by the dam's owners on October 14, 1938 indicates that a reported flood depth about 5 feet above the spillway crest caused no injury to the dam.

SECTION 6 - STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

(a) Visual Observations

The field investigation revealed no significant displacements and/or distress which would warrant the preparation of structural stability calculations based on assumed sectional properties and engineering factors.

(b) Design and Construction Data

No plans or calculations of value to a stability assessment are available for this dam.

(c) Operating Records

There are no operating records for this dam.

(d) Post Construction Changes

There are no records of past construction changes or alterations, but field investigations have revealed that extensive concrete work has been performed on the wall on the left bank, both abutment structures, the sluiceway structure, and the right end wall.

(e) Seismic Stability

The dam is located in Seismic Zone No. 2 and in accordance with recommended Phase I guidelines does not warrant seismic analysis.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS
AND REMEDIAL MEASURES

7.1 Dam Assessment

(a) Condition

Water Loom Pond Dam is in POOR condition at the present time. The spillway is in FAIR condition.

(b) Adequacy of Information

The lack of in-depth engineering data does not permit a definitive review. Therefore, the adequacy of the dam cannot be assessed from the standpoint of reviewing design and construction data. This assessment is based primarily on the visual inspection, past performance, and sound engineering judgment.

(c) Urgency

The improvements described herein should be implemented by the owner within one year of receipt of the Phase I Inspection Report.

(d) Need for Additional Investigation

Additional investigations are required as recommended in Paragraph 7.2.

7.2 Recommendations

It is recommended that the services of a registered professional engineer be retained for the following:

- (1) Rehabilitate the sluice gate structure, including the gate and operating mechanism, to serve its intended function.
- (2) Repair eroded and spalled concrete on all facing walls, abutment structures, and at the spillway.
- (3) Monitor the seepage at the penstock and right abutment section and determine the necessary remedial measures.

APPENDIX A
VISUAL INSPECTION CHECKLIST

INSPECTION TEAM ORGANIZATION

Date: November 14, 1978

NE 00355
WATER LOOM POND DAM
New Ipswich, New Hampshire
Souhegan River
NEWRB 175.09

Weather: Overcast, windy, 59°F

INSPECTION TEAM

Nicholas Carpalma	Goldberg, Zoino, Dunnieliff & Associates, Inc. (GZD)	Team Captain
Robert Minutoli	GZD	Soils
Andrew Christo	Andrew Christo Engineers (ACE)	Structural
Paul Razgha	ACE	Concrete
Richard Luranc	Resource Analysis	Hydrology

The inspection team was accompanied by Mr. Roger Inferriore, the plant manager for Warwick Mills, his plant engineer, and Mr. Patti Kesavan of the New Hampshire Water Resources Board.

CHECK LISTS FOR VISUAL INSPECTION

AREA EVALUATED	BY	CONDITION & REMARKS
Upstream concrete facing (cont.)		
Spalling	RL	Extensive over entire face of wall up to 2 inches deep. Top of wall exhibits surface spalls over 5% of its surface area.
Cracking		Considerable random cracking on face of wall exclusive of areas eroded or spalled. Top of walls exhibits a high degree of random cracking.
Exposure and staining of concrete		At water line where reinforcing is exposed.
Visible Reinforcing		Exposed at water line over 25% of length of wall.
Efflorescence	RL	Localized
DETAIL WORKS		
At Left Spillway Abutment and Downstream Training Wall		
Condition of concrete	AC	Poor
Erosion		Interface between spillway crest eroded up to 6 inches deep.
Spalling		Extensive over 50% of its vertical face. Top surface spalled in excess of 25% of its area.
Cracking	AC	Considerable random cracking on face of concrete.

CHECK LISTS FOR VISUAL INSPECTION

AREA EVALUATED	BY	CONDITION & REMARKS
<p>Condition and staining of concrete</p> <p>Visible reinforcement</p> <p>Efflorescence</p> <p>Imp. stone masonry training wall</p> <p>Seepage</p>	AC	<p>Downstream portion of abutment stained</p> <p>None noted</p> <p>Located at most of cracks</p> <p>Good condition</p> <p>None noted</p>
<p>Spillway Structure</p> <p>Condition of concrete</p> <p>Erosion</p> <p>Cracking</p> <p>Staining and staining of concrete</p> <p>Visible reinforcement</p> <p>Seepage</p> <p>Abutment structure</p> <p>Condition of concrete</p> <p>Erosion</p>	AC	<p>Surface erosion</p> <p>Two locations at its base severely eroded. 16 S.F. x 6 inches deep and 8 S.F. x 3 inches deep. Various isolated eroded pockets</p> <p>Open construction joints</p> <p>None noted</p> <p>None noted</p> <p>None noted</p> <p>Poor</p> <p>Interface between spillway crest eroded 9 to 12 inches deep. Upstream face eroded up to 15 inches at water line</p>

CHECK LISTS FOR VISUAL INSPECTION

AREA EVALUATED	BY	CONDITION & REMARKS
Spalling	AC	Vertical faces spalled 4 inches deep over approximately 50% of surface area
Cracking		Prevalent over remaining surfaces of structure.
Rusting or staining of concrete		Minor staining at base of abutment
Visible reinforcing		None noted
Efflorescence		Located at most cracks
Seepage	AC	At base of downstream end of abutment at rate of 1 gpm
2. Gate Structure		
Tyler sluice gate	PR	Gate and stem completely deteriorated. Seepage at the approximate rate of 15 to 20 gpm flows through and around gate
Operating mechanism		Non-functioning
Condition of concrete		Poor
Erosion		Extensive at base of side walls
Spalling		Side walls and upstream face severely spalled
Cracking		Extensive on side walls
Rusting or staining of concrete	PR	None noted

CHECK LISTS FOR VISUAL INSPECTION

AREA EVALUATED	BY	CONDITION & REMARKS
Visible reinforcement	PK	None noted
Efflorescence		Roof of outlet structure completely oxidized with white efflorescent formations
Seepage		See notation under "Outlet Sluice Gate"
Stone masonry		Inspected masonry on left side, entrance tunnel to spillway
RIGHT END WALL		
Condition of concrete	PK	Poor
Spalling		Top and upstream face severely spalled
Cracking		Considerable on top and front face
Reinforcing steel in concrete		None noted
Visible reinforcement		None noted
Efflorescence		At cracks
Seepage		None noted
DOWNSTREAM END		
Condition	PK	Partial. Filled with earth on embankment
Cracking		None on right face, top of wall tilted approximately 6 inches
Seepage		At the rate of 1.0 gpm at base of left embankment


November 11, 1978
ME 00355

CHECK LISTS FOR VISUAL INSPECTION		
AREA EVALUATED	BY	CONDITION & REMARKS
DEVELOPING CHANNEL	NAC	
Slope conditions:		Steep slopes on left side; moderate slopes on right side; heavy vegetation on both sides.
Loose slides or rolls:		None noted.
Entrances or debris:		Trees and branches in channel and along the bank.
Overgrowth on either side of channel:		Heavy overgrowth on both sides of channel does extend over channel; some vegetation grow- ing in the channel.
Obstructions:		Six-foot diameter penstock spans channel 75 feet downstream of dam. Bottom of penstock approxi- mately 7 feet above channel bottom.
Vegetation at upper end of dam:		None.
Vegetation along slope:		
Vegetation on downstream slope:		None noted.
Condition upstream from dam:		Channel appears stable. Some drift behind dam.
Condition downstream from dam:		None noted.

APPENDIX C
SELECTED PHOTOGRAPHS

The New Hampshire Water Resources Board (NHWRB), 37 Pleasant Street, Concord, NH 03301, maintains an extensive correspondence file for Water Loan Fund loans. Included in this file are several inspection reports, inventory reports, questionnaires, and correspondence relating to the loans. Some of the more pertinent data contained in the file are listed below.

1. NHWRB Loan Survey Inspection Report dated Sept. 24, 1971.
2. New Hampshire Water Control Commission (NHWCC) Report on Loan Inspection dated July 3, 1951.
3. Letter from Concordia Mills Lumbering Department to NHWRB re: mill power generation at Concordia Mills dated March 10, 1957.
4. NHWRB Letter to New Hampshire dated April 17, 1954.
5. NHWRB Letter to New Hampshire re: developments in New Hampshire dated April 17, 1954.
6. NHWRB Letter to New Hampshire dated 1938 with response from Concordia Mills.
7. NHWRB Inventory Report and Water Power Potential Report dated March 1957.



THE UNIVERSITY OF CHICAGO
LIBRARY
1961

UNIVERSITY OF CHICAGO
LIBRARY

1000

1000

1000

1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951

1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951


1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951
1950-1951	1950-1951	1950-1951	1950-1951	1950-1951	1950-1951


100-100000	100-100000
100-100000	100-100000
100-100000	100-100000
100-100000	100-100000

PLAN AND SECTION

100-100000	100-100000
100-100000	100-100000
100-100000	100-100000
100-100000	100-100000

[The body of the document contains several paragraphs of text that are extremely faint and illegible due to the quality of the scan. The text appears to be organized into sections, possibly separated by horizontal lines, but the specific content cannot be discerned.]





N

TO RTS 124 & 123

FORMER INLET FILLED
WITH SAND & GRAVEL

OLD MILL
END

ABANDONED
PENSTOCK

GATE STRUCTURE
(INOPERABLE)

WATER LOOM POND
USGS ELEV 927

RIVER RD

SOUEGAN RIVER

GOLDBERG, ZOINO, DUNNICLIFF & ASSOC, INC
GEOTECHNICAL CONSULTANTS
NEWTON UPPER FALLS, MASS

U.S. ARMY ENGINEER DIV NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS

SITE PLAN

FILE No. 2201

WATER LOOM POND DAM

NEW HAMPSHIRE

SCALE 1" ≈ 200'

DATE NOVEMBER 1978

APPENDIX B

		<u>Page</u>
FIGURE 1	Site Plan	B-2
FIGURE 2	Plan and Section of Dam	B-3
FIGURE 3	Front Elevation of Dam	B-4
	List of Pertinent Records not Included and Their Location	B-5

WATER LOOM POND DAM
New Ipswich, NH

November 14, 1979
NH 90355

• CHECK LISTS FOR VISUAL INSPECTION

AREA EVALUATED	BY	CONDITION & REMARKS
OPERATION AND MAINTENANCE FEATURES		
A. Reservoir regulation plan	<i>RHC</i>	None exists
B. Maintenance	<i>RHC</i>	Considerable repairs and maintenance needed at dam

N

TO RTS 124 & 123

FORMER INLET FILLED
WITH SAND & GRAVEL

OLD MILL
END

ABANDONED
PENSTOCK

GATE STRUCTURE
(INOPERABLE)

WATER LOOM POND
USGS ELEV 927

RIVER RD

SPUEGAN RIVER

➤ OVERVIEW

▷ APPENDIX C

GOLDBERG, ZOINO, DUNNCLIFF & ASSOC., INC.
GEOTECHNICAL CONSULTANTS
NEWTON UPPER FALLS, MASS

U.S. ARMY ENGINEER DIV. NEW ENGLAND
CORPS OF ENGINEERS
WALTHAM, MASS

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS

LOCATION AND ORIENTATION OF PHOTOS

FILE NO 220

WATER LOOM POND DAM

NEW HAMPSHIRE

SCALE 1" = 200'

DATE NOVEMBER 1979



1. View of downstream channel from right abutment showing penstock



2. View of right abutment from left side of spillway showing bedrock outcrops at abutment and under spillway



3. View of right abutment from downstream showing deterioration of concrete



1. View from downstream showing sluiceway with non-operational gate on upstream face of dam and deteriorated concrete of right abutment



5. View of deteriorated condition of gate operating mechanism



6. View of left spillway endwall from downstream showing deteriorated concrete




7 View from downstream showing earth filled rock crib forming left side of dam



8 View from downstream showing concrete facing



9. Detail of deteriorated concrete on downstream side of spillway



APPENDIX D
HYDROLOGIC, HYDRAULIC COMPUTATIONS

I Dam Rating Curve

Some of the physical characteristics of the Water Lowm Pond Dam spillway, not outlined are shown in the schematic sketch on page 2 based on the knowledge survey file and recent field inspection. From these are developed stage-discharge relations in the form

Datum -- Spillway crest, elev. 927.7

Free Spilling

$$Q_1 = C L H_1^{1.5} = \frac{3.2 \times 25 \times H^{1.5}}{2.0} \quad \text{sec. ft}^3$$

$$L = 25'$$


$$H_1 = H$$

1.3 Dam

$$Q_2 = C L H_2^{1.5} = \frac{2.5 \times 375 \times (H - 2.5)^{1.5}}{2.0} \quad \text{sec. ft}^3$$

$$L = 375'$$

$$H_2 = H - 2.5 \quad \text{crest elev. 922.2}$$



Schematic Cross-Section
Water Level Point Dam
(looking upstream)

2. Dam Safety - after Laminar Dam

16.05
2-7-99

21
15

2.1. Dam

$$Q_s = C H_3^{1.5} = \frac{2.8 \times 112 \times (H-3.5)^{1.5}}{(average broad-crested weir)}$$

$C = 2.8$
 $L = 112$
 $H_3 = H - 3.5$ (crest elev 931.3)

2.2. Footing

$$Q_s = C H_4^{1.5} = \frac{2.8 \times (H-2.5) \times 5 \times ((H-2.5)/2)^{1.5}}{(1:5 slope)}$$

$C = 2.8$
 $L = (H-2.5) \times 5$ (1:5 slope)
 $H_4 = (H-2.5)/2$ (avg. height)

2.3. Abutment

$$Q_s = C H_5^{1.5} = \frac{2.8 \times (H-3.5) \times 5 \times ((H-3.5)/2)^{1.5}}{(1:5 slope)}$$

$C = 2.8$
 $L = (H-3.5) \times 5$ (1:5 slope)
 $H_5 = (H-3.5)/2$ (avg. height)

and h

$h_0 = 0$ (in practice)

velocity (negligible)

A short program is written to calculate the average height, the height function of the dam, the height is shown in Fig 14, followed by graphical output and a printed case.

```

LIST
100 REM: STAGE DISCHARGE PROGRAM FOR WATER LOOM POND DAM
110 REM: PROGRAM STORED ON TAPE 18, FILE 51
120 PAGE
130 PRINT "DISCHARGE FROM WATER LOOM POND DAM AS A FUNCTION OF HEAD"
140 PRINT USING 159:
150 IMAGE 21T"HEAD"30T"DISCHARGE"
160 PRINT USING 178:
170 IMAGE 11T"(FEET)"32T"(CFS)"
180 PRINT USING 198:
190 IMAGE 10T"SLUICENWAY"5X"PENSTOCK"5X"SPILLWAY"5X"TOP OF DAM"5X"TOTAL"
200 FOR H=0 TO 13.5 STEP 0.5
210 01=3.7+75*H+1.5
220 02=0
230 03=0
240 04=0
250 05=0
260 06=0
270 07=0
280 IF H<2.5 THEN 340
290 02=2.8+37.5*(H-2.5)+1.5
300 04=2.8*(H-2.5)+5*(0.5*(H-2.5))+1.5
310 IF H<3.5 THEN 340
320 03=2.8+112*(H-3.5)+1.5
330 05=2.8*(H-3.5)+5*(0.5*(H-3.5))+1.5
340 T1=02+03+04+05
350 T2=01+T1
360 PRINT USING 379:H,06,07,01,T1,T2
370 IMAGE 21,20,10,90,130,160,140,110
380 NEXT H
390 END


```

DISCHARGE FROM WATER LOOM POND DAM AS A FUNCTION OF HEAD

HEAD (FEET)	SLUICeway	PENSTOCK	DISCHARGE (CFS)	SPILLWAY	TOP OF DAM	TOTAL
0.0	0	0	0	0	0	0
0.5	0	0	0	0	0	0
1.0	0	0	0	0	0	270
1.5	0	0	0	0	0	510
2.0	0	0	0	0	0	785
2.5	0	0	0	0	0	1097
3.0	0	0	0	0	0	1400
3.5	0	0	0	0	0	1627
4.0	0	0	0	0	0	1855
4.5	0	0	0	0	0	2082
5.0	0	0	0	0	0	2309
5.5	0	0	0	0	0	2536
6.0	0	0	0	0	0	2763
6.5	0	0	0	0	0	2990
7.0	0	0	0	0	0	3217
7.5	0	0	0	0	0	3444
8.0	0	0	0	0	0	3671
8.5	0	0	0	0	0	3898
9.0	0	0	0	0	0	4125
9.5	0	0	0	0	0	4352
10.0	0	0	0	0	0	4579
10.5	0	0	0	0	0	4806
11.0	0	0	0	0	0	5033
11.5	0	0	0	0	0	5260
12.0	0	0	0	0	0	5487
12.5	0	0	0	0	0	5714
13.0	0	0	0	0	0	5941
13.5	0	0	0	0	0	6168
14.0	0	0	0	0	0	6395
14.5	0	0	0	0	0	6622
15.0	0	0	0	0	0	6849
15.5	0	0	0	0	0	7076
16.0	0	0	0	0	0	7303
16.5	0	0	0	0	0	7530
17.0	0	0	0	0	0	7757
17.5	0	0	0	0	0	7984
18.0	0	0	0	0	0	8211
18.5	0	0	0	0	0	8438
19.0	0	0	0	0	0	8665
19.5	0	0	0	0	0	8892
20.0	0	0	0	0	0	9119
20.5	0	0	0	0	0	9346
21.0	0	0	0	0	0	9573
21.5	0	0	0	0	0	9800
22.0	0	0	0	0	0	10027
22.5	0	0	0	0	0	10254
23.0	0	0	0	0	0	10481
23.5	0	0	0	0	0	10708
24.0	0	0	0	0	0	10935
24.5	0	0	0	0	0	11162
25.0	0	0	0	0	0	11389
25.5	0	0	0	0	0	11616
26.0	0	0	0	0	0	11843
26.5	0	0	0	0	0	12070
27.0	0	0	0	0	0	12297
27.5	0	0	0	0	0	12524
28.0	0	0	0	0	0	12751
28.5	0	0	0	0	0	12978
29.0	0	0	0	0	0	13205
29.5	0	0	0	0	0	13432
30.0	0	0	0	0	0	13659
30.5	0	0	0	0	0	13886
31.0	0	0	0	0	0	14113
31.5	0	0	0	0	0	14340
32.0	0	0	0	0	0	14567
32.5	0	0	0	0	0	14794
33.0	0	0	0	0	0	15021
33.5	0	0	0	0	0	15248
34.0	0	0	0	0	0	15475
34.5	0	0	0	0	0	15702
35.0	0	0	0	0	0	15929
35.5	0	0	0	0	0	16156
36.0	0	0	0	0	0	16383
36.5	0	0	0	0	0	16610
37.0	0	0	0	0	0	16837
37.5	0	0	0	0	0	17064
38.0	0	0	0	0	0	17291
38.5	0	0	0	0	0	17518
39.0	0	0	0	0	0	17745
39.5	0	0	0	0	0	17972
40.0	0	0	0	0	0	18199
40.5	0	0	0	0	0	18426
41.0	0	0	0	0	0	18653
41.5	0	0	0	0	0	18880
42.0	0	0	0	0	0	19107
42.5	0	0	0	0	0	19334
43.0	0	0	0	0	0	19561
43.5	0	0	0	0	0	19788
44.0	0	0	0	0	0	20015
44.5	0	0	0	0	0	20242
45.0	0	0	0	0	0	20469
45.5	0	0	0	0	0	20696
46.0	0	0	0	0	0	20923
46.5	0	0	0	0	0	21150
47.0	0	0	0	0	0	21377
47.5	0	0	0	0	0	21604
48.0	0	0	0	0	0	21831
48.5	0	0	0	0	0	22058
49.0	0	0	0	0	0	22285
49.5	0	0	0	0	0	22512
50.0	0	0	0	0	0	22739
50.5	0	0	0	0	0	22966
51.0	0	0	0	0	0	23193
51.5	0	0	0	0	0	23420
52.0	0	0	0	0	0	23647
52.5	0	0	0	0	0	23874
53.0	0	0	0	0	0	24101
53.5	0	0	0	0	0	24328
54.0	0	0	0	0	0	24555
54.5	0	0	0	0	0	24782
55.0	0	0	0	0	0	25009
55.5	0	0	0	0	0	25236
56.0	0	0	0	0	0	25463
56.5	0	0	0	0	0	25690
57.0	0	0	0	0	0	25917
57.5	0	0	0	0	0	26144
58.0	0	0	0	0	0	26371
58.5	0	0	0	0	0	26598
59.0	0	0	0	0	0	26825
59.5	0	0	0	0	0	27052
60.0	0	0	0	0	0	27279
60.5	0	0	0	0	0	27506
61.0	0	0	0	0	0	27733
61.5	0	0	0	0	0	27960
62.0	0	0	0	0	0	28187
62.5	0	0	0	0	0	28414
63.0	0	0	0	0	0	28641
63.5	0	0	0	0	0	28868
64.0	0	0	0	0	0	29095
64.5	0	0	0	0	0	29322
65.0	0	0	0	0	0	29549
65.5	0	0	0	0	0	29776
66.0	0	0	0	0	0	30003
66.5	0	0	0	0	0	30230
67.0	0	0	0	0	0	30457
67.5	0	0	0	0	0	30684
68.0	0	0	0	0	0	30911
68.5	0	0	0	0	0	31138
69.0	0	0	0	0	0	31365
69.5	0	0	0	0	0	31592
70.0	0	0	0	0	0	31819
70.5	0	0	0	0	0	32046
71.0	0	0	0	0	0	32273
71.5	0	0	0	0	0	32500
72.0	0	0	0	0	0	32727
72.5	0	0	0	0	0	32954
73.0	0	0	0	0	0	33181
73.5	0	0	0	0	0	33408
74.0	0	0	0	0	0	33635
74.5	0	0	0	0	0	33862
75.0	0	0	0	0	0	34089
75.5	0	0	0	0	0	34316
76.0	0	0	0	0	0	34543
76.5	0	0	0	0	0	34770
77.0	0	0	0	0	0	34997
77.5	0	0	0	0	0	35224
78.0	0	0	0	0	0	35451
78.5	0	0	0	0	0	35678
79.0	0	0	0	0	0	35905
79.5	0	0	0	0	0	36132
80.0	0	0	0	0	0	36359
80.5	0	0	0	0	0	36586
81.0	0	0	0	0	0	36813
81.5	0	0	0	0	0	37040
82.0	0	0	0	0	0	37267
82.5	0	0	0	0	0	37494
83.0	0	0	0	0	0	37721
83.5	0	0	0	0	0	37948
84.0	0	0	0	0	0	38175
84.5	0	0	0	0	0	38402
85.0	0	0	0	0	0	38629
85.5	0	0	0	0	0	38856
86.0	0	0	0	0	0	39083
86.5	0	0	0	0	0	39310
87.0	0	0	0	0	0	39537
87.5	0	0	0	0	0	39764
88.0	0	0	0	0	0	39991
88.5	0	0	0	0	0	40218
89.0	0	0	0	0	0	40445
89.5	0	0	0	0	0	40672
90.0	0	0	0	0	0	40899
90.5	0	0	0	0	0	41126
91.0	0	0	0	0	0	41353
91.5	0	0	0	0	0	41580
92.0	0	0	0	0	0	41807
92.5	0	0	0	0	0	42034
93.0	0	0	0	0	0	42261
93.5	0	0	0	0	0	42488
94.0	0	0	0	0	0	42715
94.5	0	0	0	0	0	42942
95.0	0	0	0	0	0	43169
95.5	0	0	0	0	0	43396
96.0	0	0	0	0	0	43623
96.5	0	0	0	0	0	43850
97.0	0	0	0	0	0	44077
97.5	0	0	0	0	0	44304
98.0	0	0	0	0	0	44531
98.5	0	0	0	0	0	44758
99.0	0	0	0	0	0	44985
99.5	0	0	0	0	0	45212
100.0	0	0	0	0	0	45439

5/1

STAGE-DISCHARGE CURVE AT WATER LOOM POND



22

10/2/79 10:00 AM Walter Loom Prof/Dim 2-5-79 76

The following discussion is intended to show that
 the above theorem can be extended to the case
 that the function $f(x)$ is not necessarily reduced
 to zero at the end of the interval. The theorem
 then becomes:

The lower part contains a
 considerable part of the
 same material as the upper part, the
 same material as the lower part, in a
 different position.

6th Dam Safety Inspector Leon Kent Van

LEI
5-7-79

The

High bridge 1 3/4

Smith, constructed High bridge
and concrete structure bridge was
built last summer on stream a large
dam for the dam is not subject to any
operation or maintenance. The dam is
in good shape.

Check on the dam and the bridge
and all the bridge is in good shape.

2-1-79

1-1-79

2-1-79

2-1-79

2-1-79

2-1-79

The dam is in good shape and the bridge
is in good shape and the dam is in good shape.

The dam is in good shape and the bridge
is in good shape and the dam is in good shape.
The dam is in good shape and the bridge
is in good shape and the dam is in good shape.

105th Dam Safety Water Loss Pmt/Dm

2011
2-1-28

15
1/-

Peak Water outflow from High Bridge

$$= 2833 + 2000 = 4833 \text{ CFS}$$

In this case, given that the flow is from the
dam to the right, the flow is to the right of the
High Bridge. The flow

Don't think you're looking for a High Bridge

Rated peak 1911

1911

1911

1911

1911

Can't think you're looking for a High Bridge

1911

1911

1911

1911

1911

1911

1911

1911

1911

1911

1911

1911

Routing, 1, action

$$Q_{P2} = Q_{P1} \left(1 - \frac{V'}{S}\right)$$

Q_{P2} = total outflow peak of dam break

Q_{P1} = 3400 CFS (dam break compound peak inflow)

V' = 665 AF (total volume of dam break wave)

V' = 665 $\left(1 - \frac{Q_{P2}}{3400}\right)$ (surcharge storage vol. required to reduce outflow peak to Q_{P2})

Q_{P2}	V'	Stage
3400	0	0.0
2400	240	0.1
1400	540	0.2

~~Don~~ Don Silby after Loan Rep / Done

2-7-27

15/

2 Aug - 11 Aug

The only case truly within the I.E. Rule
I think in terms of change in time with the
following assumptions and qualifications.

- There is a steady flow component around each of the four points, and a weak flow from the front point to the rear point.
- Only the flow from the front point is visible. The flow from the rear point is not visible. The flow from the side points is not visible.
- The flow from the front point is the same as the flow from the rear point. The flow from the side points is the same as the flow from the front point.

constant size by flow component conditions and
high bridge at time of failure

2000-2001 CFS

Small Stage Package
and smaller than
the 10' x 10' (the
original)

Thymus praecox

large (one 11 1/2 lbs)

1. A1


From the 1970s
and 1980s

150

(1994, 1995, 1996)

14/52

STAGE - STORAGE CURVE High Bridge



Calculated from
reach 2 channel top-
width $\frac{B}{3}$

Jan 1955

Don Sibley Water Level Pond Don

2-7-79

13/52

Large Storage - High Bridge


H	Area	Avg. Area	Length	A Vol	Vol
0	0			0	0
1	27.5	13.8	110	3030	102
2	27.5	13.8	110	3030	102
3	27.5	13.8	110	3030	102
4	27.5	13.8	110	3030	102
5	27.5	13.8	110	3030	102
6	27.5	13.8	110	3030	102
7	27.5	13.8	110	3030	102
8	27.5	13.8	110	3030	102
9	27.5	13.8	110	3030	102
10	27.5	13.8	110	3030	102
11	27.5	13.8	110	3030	102
12	27.5	13.8	110	3030	102
13	27.5	13.8	110	3030	102
14	27.5	13.8	110	3030	102
15	27.5	13.8	110	3030	102
16	27.5	13.8	110	3030	102
17	27.5	13.8	110	3030	102
18	27.5	13.8	110	3030	102
19	27.5	13.8	110	3030	102
20	27.5	13.8	110	3030	102
21	27.5	13.8	110	3030	102
22	27.5	13.8	110	3030	102
23	27.5	13.8	110	3030	102
24	27.5	13.8	110	3030	102
25	27.5	13.8	110	3030	102
26	27.5	13.8	110	3030	102
27	27.5	13.8	110	3030	102
28	27.5	13.8	110	3030	102
29	27.5	13.8	110	3030	102
30	27.5	13.8	110	3030	102
31	27.5	13.8	110	3030	102
32	27.5	13.8	110	3030	102
33	27.5	13.8	110	3030	102
34	27.5	13.8	110	3030	102
35	27.5	13.8	110	3030	102
36	27.5	13.8	110	3030	102
37	27.5	13.8	110	3030	102
38	27.5	13.8	110	3030	102
39	27.5	13.8	110	3030	102
40	27.5	13.8	110	3030	102
41	27.5	13.8	110	3030	102
42	27.5	13.8	110	3030	102
43	27.5	13.8	110	3030	102
44	27.5	13.8	110	3030	102
45	27.5	13.8	110	3030	102
46	27.5	13.8	110	3030	102
47	27.5	13.8	110	3030	102
48	27.5	13.8	110	3030	102
49	27.5	13.8	110	3030	102
50	27.5	13.8	110	3030	102
51	27.5	13.8	110	3030	102
52	27.5	13.8	110	3030	102
53	27.5	13.8	110	3030	102
54	27.5	13.8	110	3030	102
55	27.5	13.8	110	3030	102
56	27.5	13.8	110	3030	102
57	27.5	13.8	110	3030	102
58	27.5	13.8	110	3030	102
59	27.5	13.8	110	3030	102
60	27.5	13.8	110	3030	102
61	27.5	13.8	110	3030	102
62	27.5	13.8	110	3030	102
63	27.5	13.8	110	3030	102
64	27.5	13.8	110	3030	102
65	27.5	13.8	110	3030	102
66	27.5	13.8	110	3030	102
67	27.5	13.8	110	3030	102
68	27.5	13.8	110	3030	102
69	27.5	13.8	110	3030	102
70	27.5	13.8	110	3030	102
71	27.5	13.8	110	3030	102
72	27.5	13.8	110	3030	102
73	27.5	13.8	110	3030	102
74	27.5	13.8	110	3030	102
75	27.5	13.8	110	3030	102
76	27.5	13.8	110	3030	102
77	27.5	13.8	110	3030	102
78	27.5	13.8	110	3030	102
79	27.5	13.8	110	3030	102
80	27.5	13.8	110	3030	102
81	27.5	13.8	110	3030	102
82	27.5	13.8	110	3030	102
83	27.5	13.8	110	3030	102
84	27.5	13.8	110	3030	102
85	27.5	13.8	110	3030	102
86	27.5	13.8	110	3030	102
87	27.5	13.8	110	3030	102
88	27.5	13.8	110	3030	102
89	27.5	13.8	110	3030	102
90	27.5	13.8	110	3030	102
91	27.5	13.8	110	3030	102
92	27.5	13.8	110	3030	102
93	27.5	13.8	110	3030	102
94	27.5	13.8	110	3030	102
95	27.5	13.8	110	3030	102
96	27.5	13.8	110	3030	102
97	27.5	13.8	110	3030	102
98	27.5	13.8	110	3030	102
99	27.5	13.8	110	3030	102
100	27.5	13.8	110	3030	102

13/32

STAGE-DISCHARGE CURVE

High Bridge

0.000002 (1012)



U.S. GEOLOGICAL SURVEY

See #
105

San Carlos Water Level Pond Dam

2-7-79

7/32


- Dam is 115' x 22' wide at crest
box culvert is roughly equivalent to
one row structure

H	Q
5	1270
10	2400
15	3600
20	4800
25	6000
30	7200

Stage Change due to Page 17

Stage behind High Bridge is
estimated from the Reach 1 channel
properties

$$S = \frac{1' \text{ rise}}{115' \text{ run}}$$



The stage behind the bridge is 1.15' above

the stage at the dam


Lab #
165

Dam Safety Water Loss Pond Dam

10/11
7-77

10/32

High Bridge & Stage (207)



High Bridge Configuration

perform the rating, a stage storage
and a stage-discharge curve need to be
developed for High Bridge

Stage-Discharge Curve -- Page 11

- The bridge below 12'-15' will allow
water to flow by. Water will
not flow over the bridge.
- The bridge height control is assumed
and will be used to calculate
the stage-discharge curve.

$$Q = 1.49 A R^{2/3} S^{1/2}$$

$$H = 1.5$$

$$Q = 1.49 A R^{2/3} S^{1/2}$$

$$Q = 1.49 A R^{2/3} S^{1/2}$$

$$H = 1.5$$

$$Q = 1.49 A R^{2/3} S^{1/2}$$

DEPTH	ELEV	AREA	WPER	H/D-R	AR2\3	Q
0.0	900.0	0.0	0.0	0.0	0.0	0.0
1.0	901.0	27.5	30.4	0.5	25.2	92.4
2.0	902.0	60.5	35.5	1.2	84.2	304.3
3.0	903.0	97.5	41.2	2.4	173.3	622.6
4.0	904.0	140.0	46.5	4.0	291.8	1048.4
5.0	905.0	205.0	56.0	5.4	364.3	1308.5
6.0	906.0	295.0	66.0	7.5	620.4	2228.5
7.0	907.0	395.0	107.0	9.5	944.0	3391.0
8.0	908.0	505.0	117.2	11.5	1338.0	4806.4
9.0	909.0	625.0	127.4	14.5	1805.6	6486.2
10.0	910.0	755.0	137.0	16.2	2350.5	8442.8
11.0	911.0	895.0	147.0	17.5	2975.5	10688.7
12.0	912.0	1045.0	158.2	19.2	3684.7	13236.5
13.0	913.0	1205.0	168.4	21.2	4481.5	16098.7
14.0	914.0	1375.0	178.5	22.8	5369.3	19287.0
15.0	915.0	1555.0	188.0	23.8	6351.4	22816.1
16.0	916.0	1745.0	198.0	25.0	7431.5	26695.5
17.0	917.0	1945.0	209.2	26.8	8612.3	30938.9
18.0	918.0	2155.0	219.4	28.4	9898.8	35557.4
19.0	919.0	2375.0	229.5	30.5	11291.2	40563.0
20.0	920.0	2605.0	239.6	32.9	12796.2	45967.2
21.0	921.0	2845.0	249.8	34.4	14414.8	51781.7
22.0	922.0	3095.0	260.0	36.9	16150.7	58017.6
23.0	923.0	3355.0	270.2	39.4	18007.1	64686.1
24.0	924.0	3625.0	280.4	42.4	19987.0	71798.3
25.0	925.0	3905.0	290.6	45.4	22093.4	79365.2

REACH01 - WATER LOOM POND

145 Dam Safety Water Level and Dam WWT 2-7-77 8/5

$$Q = \frac{1}{2} (130 + \sqrt{3}) \cdot 16.1 \frac{1}{2} = 341.5 \text{ CFS}$$


use 342 CFS

Downstream Flooding

Reach 1

Reach 1 extends from the dam upper crest downstream to High Bridge. It contains several properties and cross section as the 1st reach of water level.

$$K = 1.07, C = 1.007$$



A sample EASIO program was used to calculate existing stage and other channel properties shown on the following page.

Since there are no structures endangered or flooding during this reach the calculations were made to estimate the tailwater at dam failure and to estimate the stage stage function behind High Bridge (next paragraph).

High Bridge

The first step in the calculation of the stage function behind the High Bridge is to determine the stage function at the dam. The stage function at the dam is determined by the stage function at the dam. The stage function at the dam is determined by the stage function at the dam. The stage function at the dam is determined by the stage function at the dam. The stage function at the dam is determined by the stage function at the dam.

105th Dam Safety


Water Loom Pond Dam

CHF
2-7-79 7/1

II Dam Failure Analysis

Because the spillway and R/S of the dam are solid concrete structures founded on rock, it will be assumed that the critical failure section will be the U.S. of the dam and the critical pool elevation will be that which just overtops the section, elev. 103.5. (H = 5.6'). A simplified view of this section is sketched below.

A. Looking upstream



Normal at face of overtopping

Use $\gamma = 150 \text{ pcf}$ (from dam safety spec, rounded up from 145 pcf to be conservative)
 Dam height (H) = 5.6'

$$X = \frac{H^2}{2 \times 150 \times 5.6} \times \frac{1}{2}$$

$X = 0.27$ (with a 4x dam section at 1/2 height)

to 2.4 ft below crest height 1 ft above toe
 (CHF spec. 10 ft min. for 100 ft dam)

15th June 2014 Letter from Prof Dan 275 277 7/

Programme for ... the ...
... programme ...
... 24-5


...
...
...
...

```


1000  REM: STAGE DISCHARGE PROGRAM FOR OTIS COMPANY DAM # 1, JOB 165
1001  REM: ON TAPE 10, FILE 57
1002  REM:
1003  REM: DISCHARGE FROM OTIS COMPANY DAM # 1 AS A FUNCTION OF HEAD"
1004  REM:
1005  REM: USING 152:
1006  REM: << 2<"HEAD"30T"DISCHARGE"
1007  REM: USING 170:
1008  REM: IT"CEET)"32T"(CFS)"
1009  REM: USING 190:
1010  REM: 15T"TOTAL"8X"LEFT BANK"8X"RIGHT BANK"8X"SPILLWAY"
1011  REM:
1012  REM: H=0 TO 7 STEP 0.25
1013  REM:
1014  REM:
1015  REM:
1016  REM:
1017  REM:
1018  REM:
1019  REM:
1020  REM:
1021  REM:
1022  REM:
1023  REM:
1024  REM:
1025  REM:
1026  REM:
1027  REM:
1028  REM:
1029  REM:
1030  REM:
1031  REM:
1032  REM:
1033  REM:
1034  REM:
1035  REM:
1036  REM:
1037  REM:
1038  REM:
1039  REM:
1040  REM:
1041  REM:
1042  REM:
1043  REM:
1044  REM:
1045  REM:
1046  REM:
1047  REM:
1048  REM:
1049  REM:
1050  REM:
1051  REM:
1052  REM:
1053  REM:
1054  REM:
1055  REM:
1056  REM:
1057  REM:
1058  REM:
1059  REM:
1060  REM:
1061  REM:
1062  REM:
1063  REM:
1064  REM:
1065  REM:
1066  REM:
1067  REM:
1068  REM:
1069  REM:
1070  REM:
1071  REM:
1072  REM:
1073  REM:
1074  REM:
1075  REM:
1076  REM:
1077  REM:
1078  REM:
1079  REM:
1080  REM:
1081  REM:
1082  REM:
1083  REM:
1084  REM:
1085  REM:
1086  REM:
1087  REM:
1088  REM:
1089  REM:
1090  REM:
1091  REM:
1092  REM:
1093  REM:
1094  REM:
1095  REM:
1096  REM:
1097  REM:
1098  REM:
1099  REM:
1100  REM:
1101  REM:
1102  REM:
1103  REM:
1104  REM:
1105  REM:
1106  REM:
1107  REM:
1108  REM:
1109  REM:
1110  REM:
1111  REM:
1112  REM:
1113  REM:
1114  REM:
1115  REM:
1116  REM:
1117  REM:
1118  REM:
1119  REM:
1120  REM:
1121  REM:
1122  REM:
1123  REM:
1124  REM:
1125  REM:
1126  REM:
1127  REM:
1128  REM:
1129  REM:
1130  REM:
1131  REM:
1132  REM:
1133  REM:
1134  REM:
1135  REM:
1136  REM:
1137  REM:
1138  REM:
1139  REM:
1140  REM:
1141  REM:
1142  REM:
1143  REM:
1144  REM:
1145  REM:
1146  REM:
1147  REM:
1148  REM:
1149  REM:
1150  REM:
1151  REM:
1152  REM:
1153  REM:
1154  REM:
1155  REM:
1156  REM:
1157  REM:
1158  REM:
1159  REM:
1160  REM:
1161  REM:
1162  REM:
1163  REM:
1164  REM:
1165  REM:
1166  REM:
1167  REM:
1168  REM:
1169  REM:
1170  REM:
1171  REM:
1172  REM:
1173  REM:
1174  REM:
1175  REM:
1176  REM:
1177  REM:
1178  REM:
1179  REM:
1180  REM:
1181  REM:
1182  REM:
1183  REM:
1184  REM:
1185  REM:
1186  REM:
1187  REM:
1188  REM:
1189  REM:
1190  REM:
1191  REM:
1192  REM:
1193  REM:
1194  REM:
1195  REM:
1196  REM:
1197  REM:
1198  REM:
1199  REM:
1200  REM:
1201  REM:
1202  REM:
1203  REM:
1204  REM:
1205  REM:
1206  REM:
1207  REM:
1208  REM:
1209  REM:
1210  REM:
1211  REM:
1212  REM:
1213  REM:
1214  REM:
1215  REM:
1216  REM:
1217  REM:
1218  REM:
1219  REM:
1220  REM:
1221  REM:
1222  REM:
1223  REM:
1224  REM:
1225  REM:
1226  REM:
1227  REM:
1228  REM:
1229  REM:
1230  REM:
1231  REM:
1232  REM:
1233  REM:
1234  REM:
1235  REM:
1236  REM:
1237  REM:
1238  REM:
1239  REM:
1240  REM:
1241  REM:
1242  REM:
1243  REM:
1244  REM:
1245  REM:
1246  REM:
1247  REM:
1248  REM:
1249  REM:
1250  REM:
1251  REM:
1252  REM:
1253  REM:
1254  REM:
1255  REM:
1256  REM:
1257  REM:
1258  REM:
1259  REM:
1260  REM:
1261  REM:
1262  REM:
1263  REM:
1264  REM:
1265  REM:
1266  REM:
1267  REM:
1268  REM:
1269  REM:
1270  REM:
1271  REM:
1272  REM:
1273  REM:
1274  REM:
1275  REM:
1276  REM:
1277  REM:
1278  REM:
1279  REM:
1280  REM:
1281  REM:
1282  REM:
1283  REM:
1284  REM:
1285  REM:
1286  REM:
1287  REM:
1288  REM:
1289  REM:
1290  REM:
1291  REM:
1292  REM:
1293  REM:
1294  REM:
1295  REM:
1296  REM:
1297  REM:
1298  REM:
1299  REM:
1300  REM:
1301  REM:
1302  REM:
1303  REM:
1304  REM:
1305  REM:
1306  REM:
1307  REM:
1308  REM:
1309  REM:
1310  REM:
1311  REM:
1312  REM:
1313  REM:
1314  REM:
1315  REM:
1316  REM:
1317  REM:
1318  REM:
1319  REM:
1320  REM:
1321  REM:
1322  REM:
1323  REM:
1324  REM:
1325  REM:
1326  REM:
1327  REM:
1328  REM:
1329  REM:
1330  REM:
1331  REM:
1332  REM:
1333  REM:
1334  REM:
1335  REM:
1336  REM:
1337  REM:
1338  REM:
1339  REM:
1340  REM:
1341  REM:
1342  REM:
1343  REM:
1344  REM:
1345  REM:
1346  REM:
1347  REM:
1348  REM:
1349  REM:
1350  REM:
1351  REM:
1352  REM:
1353  REM:
1354  REM:
1355  REM:
1356  REM:
1357  REM:
1358  REM:
1359  REM:
1360  REM:
1361  REM:
1362  REM:
1363  REM:
1364  REM:
1365  REM:
1366  REM:
1367  REM:
1368  REM:
1369  REM:
1370  REM:
1371  REM:
1372  REM:
1373  REM:
1374  REM:
1375  REM:
1376  REM:
1377  REM:
1378  REM:
1379  REM:
1380  REM:
1381  REM:
1382  REM:
1383  REM:
1384  REM:
1385  REM:
1386  REM:
1387  REM:
1388  REM:
1389  REM:
1390  REM:
1391  REM:
1392  REM:
1393  REM:
1394  REM:
1395  REM:
1396  REM:
1397  REM:
1398  REM:
1399  REM:
1400  REM:
1401  REM:
1402  REM:
1403  REM:
1404  REM:
1405  REM:
1406  REM:
1407  REM:
1408  REM:
1409  REM:
1410  REM:
1411  REM:
1412  REM:
1413  REM:
1414  REM:
1415  REM:
1416  REM:
1417  REM:
1418  REM:
1419  REM:
1420  REM:
1421  REM:
1422  REM:
1423  REM:
1424  REM:
1425  REM:
1426  REM:
1427  REM:
1428  REM:
1429  REM:
1430  REM:
1431  REM:
1432  REM:
1433  REM:
1434  REM:
1435  REM:
1436  REM:
1437  REM:
1438  REM:
1439  REM:
1440  REM:
1441  REM:
1442  REM:
1443  REM:
1444  REM:
1445  REM:
1446  REM:
1447  REM:
1448  REM:
1449  REM:
1450  REM:
1451  REM:
1452  REM:
1453  REM:
1454  REM:
1455  REM:
1456  REM:
1457  REM:
1458  REM:
1459  REM:
1460  REM:
1461  REM:
1462  REM:
1463  REM:
1464  REM:
1465  REM:
1466  REM:
1467  REM:
1468  REM:
1469  REM:
1470  REM:
1471  REM:
1472  REM:
1473  REM:
1474  REM:
1475  REM:
1476  REM:
1477  REM:
1478  REM:
1479  REM:
1480  REM:
1481  REM:
1482  REM:
1483  REM:
1484  REM:
1485  REM:
1486  REM:
1487  REM:
1488  REM:
1489  REM:
1490  REM:
1491  REM:
1492  REM:
1493  REM:
1494  REM
```

DISCHARGE FROM OTIS COMPANY DAM # 1 AS A FUNCTION OF HEAD

HEAD (FEET)	TOTAL	DISCHARGE (CFS) LEFT BANK	RIGHT BANK	SPILLWAY
0.0	0	0	0	0
0.5	38	0	0	38
1.0	109	0	0	109
1.5	199	0	0	199
2.0	307	0	0	307
2.5	429	0	0	429
3.0	564	0	0	564
3.5	710	0	0	710
4.0	868	0	0	868
4.5	1036	0	0	1036
5.0	1213	0	0	1213
5.5	1400	0	0	1400
6.0	1595	0	0	1595
6.5	1798	0	0	1798
7.0	2010	0	0	2010
7.5	2229	0	0	2229
8.0	2455	0	10	2455
8.5	2689	0	10	2689
9.0	2930	0	10	2930
9.5	3177	0	10	3177
10.0	3431	0	10	3431
10.5	3692	0	10	3692
11.0	3959	0	10	3959
11.5	4232	0	10	4232
12.0	4510	0	10	4510
12.5	4795	0	10	4795
13.0	5086	0	10	5086
13.5	5382	0	10	5382
14.0	5684	0	10	5684



STAGE-DISCHARGE CURVE AT OTIS COMPANY DAM # 1



10/2

III. 1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

$$P_{100} = 100 A^{1.05} - \frac{100}{1.05}$$

1. 1. 1. Indicators


1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators

1. 1. 1. Indicators



Drainage Area Delineation
Water Loom Pond Dam
Drainage Area = 23.1 sq. mi
Scale 1:250,000

Dr. J. H. ...

26

Historic ...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

7. You say that the 13th of May

is the day

of the day when the day
of the day

of the day when the day
of the day

of the day when the day
of the day

of the day when the day
of the day

of the day when the day
of the day

of the day when the day
of the day

of the day when the day
of the day

of the day when the day
of the day

of the day when the day
of the day

of the day when the day
of the day

2. John Wiley & Sons, Inc. 111 Fifth Avenue New York 100

Dear Sir: I am writing you to
inform you that I have received
your letter of the 10th of June and
that I am sorry to hear that

you are having trouble with the
machine. I am sorry to hear that
you are having trouble with the
machine. I am sorry to hear that
you are having trouble with the
machine.

Very truly yours,

John Wiley & Sons, Inc.

Enclosed for you is a check for

\$100.00.

I am sorry to hear that you are

having trouble with the machine.

I am sorry to hear that you are

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page. Some words like "The" and "and" are visible.]



My dear Mr. [unclear]

Very truly yours,

[unclear]

[unclear]

[unclear]

[unclear]

[unclear]

[unclear]

RECEIVED
JAN 11 1961
U.S. AIR FORCE

END

FILMED

8-85

DTIC